

# **SAFETY AND EMISSIONS** **RECALL NOTICE**


FG110K1AT Tillers

## **FUEL TANK GROMMET**

Check below to see if your tiller is affected by this recall.

### **FG110K1AT**

Engine Serial  
Number Location



Frame Serial Number Range*	Affected Engine Serial Numbers
FAAA- 1262887 ~ 1267393	GCALT- 1696948 ~ 1700567
* Not all tillers in the frame serial number range are affected by this recall. You must check the engine serial number to verify affected units.	

### **⚠ WARNING**

Gasoline is highly flammable and explosive. You can be burned or seriously injured if gasoline from a leaking fuel tank is ignited. If the fuel tank is leaking:

- Move the tiller away from any source of ignition.
- Drain the fuel tank into an approved container.
- Do not use the tiller until it has been repaired.

**Consumers should immediately stop using the recalled tiller and contact a Honda Power Equipment dealer for a free repair.**

### ***What is the problem?***

The fuel tank grommet (located on the side of the fuel tank) on affected tillers may not have been properly manufactured and could crack or tear. If this occurs, the grommet could dislodge and result in a fuel leak.

### ***What should you do?***

Stop using any tiller with an engine in the affected range until the fuel tank assembly has been replaced. Please contact a servicing Honda Power Equipment dealer to make an appointment to have your tiller repaired free of charge. Transportation of the tiller to and from the dealer is the responsibility of the owner. If you need assistance locating a servicing dealer, please visit our website: [www.HondaPowerEquipment.com](http://www.HondaPowerEquipment.com), or contact us at (888) 888-3139.

In cooperation with the U.S. Consumer Product Safety Commission,  
the U.S. Environmental Protection Agency, and the California Air Resources Board