

American Honda Motor Co., Inc.

# **SAFETY RECALL NOTICE**

HS724, HS928, HS1132 Snowblowers


## **FUEL TANK JOINT**

Check below to see if your snowblower is affected by this recall.

**HS724, HS928, HS1132**

**Frame Serial Number Range**

HS724	SZBE-1037913 ~ 1046577
HS928	SZAS-1151080 ~ 1169012
HS1132	SZBF-1018734 ~ 1025998



### **⚠ WARNING**

Gasoline is highly flammable and explosive. You can be burned or seriously injured if gasoline from a leaking fuel tank is ignited. If the fuel tank is leaking:

- Move the snowblower away from any source of ignition.
- Drain the fuel tank into an approved container.
- Do not use the snowblower until it has been repaired.

**Consumers should immediately stop using the recalled snowblower and contact a Honda Power Equipment dealer for a free repair.**

### ***What is the problem?***

Affected snowblowers may, over time, begin seeping fuel from the fuel tank joint O-ring, located on the underside of the fuel tank. If the seepage becomes severe, fuel will begin to drip, increasing the risk of a fire.

### ***What should you do?***

Stop using any snowblower within the affected serial number range until the fuel tank joint and O-ring have been replaced. Please contact a servicing Honda Power Equipment dealer to make an appointment to have your snowblower repaired free of charge. If you need assistance locating a servicing dealer, please visit our website: [www.HondaPowerEquipment.com](http://www.HondaPowerEquipment.com), or call us at our recall line (888) 888-3139.

In cooperation with the U.S. Consumer Product Safety Commission